

AD-A161 035

A USER'S MANUAL FOR THE FIT PROGRAM: A MODEL FOR  
SMOOTHING RAW DATA(U) ARMY BALLISTIC RESEARCH LAB  
ABERDEEN PROVING GROUND MD D M PETRO OCT 85

1/1

UNCLASSIFIED

BRL-MR-3472


F/G 12/1

ML

END

FILMED

DTIC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A161 035

AD

MEMORANDUM REPORT BRL-MR-3472

A USER'S MANUAL FOR THE FIT PROGRAM:  
A MODEL FOR SMOOTHING RAW DATA

Denice M. Petro

October 1985

DTIC

SELECTED

NOV 8 1985

S

A

DTIC FILE COPY

APPROVED FOR PUBLIC RELEASE. DISTRIBUTION UNLIMITED.

US ARMY BALLISTIC RESEARCH LABORATORY  
ABERDEEN PROVING GROUND, MARYLAND

85 11 08 004

Destroy this report when it is no longer needed.  
Do not return it to the originator.

Additional copies of this report may be obtained  
from the National Technical Information Service,  
U. S. Department of Commerce, Springfield, Virginia  
22161.

The findings in this report are not to be construed as an official  
Department of the Army position, unless so designated by other  
authorized documents.

The use of trade names or manufacturers' names in this report  
does not constitute indorsement of any commercial product.

## UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER <b>MEMORANDUM REPORT BRL-MR-3472</b>	2. GOVT ACCESSION NO. <b>AD-A161035</b>	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) A USER'S MANUAL FOR THE FIT PROGRAM: A MODEL FOR SMOOTHING RAW DATA		5. TYPE OF REPORT & PERIOD COVERED
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s)  DENICE M. PETRO	8. CONTRACT OR GRANT NUMBER(s)	
9. PERFORMING ORGANIZATION NAME AND ADDRESS <b>US Army Ballistic Research Laboratory ATTN: SLCBR-SE ABERDEEN PROVING GROUND, MD 21005-5066</b>		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS <b>1L162618AH80</b>
11. CONTROLLING OFFICE NAME AND ADDRESS <b>US Army Ballistic Research Laboratory ATTN: SLCBR-DD-T ABERDEEN PROVING GROUND, MD 21005-5066</b>		12. REPORT DATE <b>October 1985</b>
		13. NUMBER OF PAGES <b>32</b>
14. MONITORING AGENCY NAME & ADDRESS(if different from Controlling Office)		15. SECURITY CLASS. (of this report)  <b>UNCLASSIFIED</b>
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for Public Release; Distribution Unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Data Analysis Smoothing Time Series Analysis		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) FIT is a Fortran 77 program which fits a smooth curve to raw data. The program finds the trends inherent in the data (the peaks, valleys, slopes, etc.) and produces a set of modified data points, which can be plotted using any available graphics package. It is easily used without much knowledge of the underlying techniques and can be employed repeatedly to the subsequent smoothed data sets to achieve any smoothness desired. However, some care must be taken, since the input data must be equally spaced in the independent variable with		

**UNCLASSIFIED**

**SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)**

only a few missing data points. This report covers input preparation, output expectation, technique explanation and provides a program listing in the appendix.

**UNCLASSIFIED**

**SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)**

## TABLE OF CONTENTS

	Page
LIST OF ILLUSTRATIONS .....	5
LIST OF TABLES .....	7
INTRODUCTION .....	9
INPUT .....	9
OUTPUT .....	12
METHODOLOGY .....	20
SUMMARY .....	21
REFERENCES .....	21
APPENDIX: PROGRAM LISTING .....	23
DISTRIBUTION LIST .....	31

A-1



## LIST OF ILLUSTRATIONS

	Page
1. Data Before and After Using the FIT Program .....	10

## LIST OF TABLES

	Page
1. Sample Data File I (No Missing Values) .....	11
2. Sample Data File II (Missing Values) .....	12
3. Output File for Sample Data File I.....	13
4. Output File for Sample Data File II.....	16
5. Sample Output File When Inadequate Fill-In Parameter Given.....	19

## INTRODUCTION

FIT is a Fortran 77 program which fits a smooth curve to raw data. The program finds the trends inherent in the data (the peaks, valleys, slopes, etc.) and produces a set of modified data points, which can be plotted using any available graphics package. Figure 1 illustrates the improvement this program can make. The scatter plot represents the raw data before using the program; while, the curve represents the smoothed data afterwards. However, care must be taken in using this program, since the input data must meet certain criteria explained in a later section.

This report is intended to teach the use of the program. It is structured to guide the reader through input preparation (with sample inputs provided), output expectation (sample outputs provided, as well), and technique explanation. No user manual would be complete without a program listing located in the appendix.

## INPUT

Basically, the data file is composed of an options line, maybe another line with a single number, followed by N (up to 750) data points, one pair per line. The program expects the points to be sequential, i.e., the independent variable of each is incremented by a constant between pairs. Even though a few data points are missing, the program can still be used; however, these points need to be filled in (which the program can do for you when you select a certain option). Let us begin by explaining the various options.

The program can be run in various modes by selecting options from the following list: "e," "f," "n," "s," and/or "x." The "e" option echoes the input data; while the "f" option fills in missing data. A smoothing of the errors is not to be done with the "n" option; while smoothing of the data and the errors is to be done with the "s" option. The "x" option causes extra printing of the partially smoothed data after each step of the process. All five options can be chosen in many combinations; however, the "n" option is useless unless the "s" option has been chosen. The options may appear anywhere in the first 40 columns of the first line of the data file in lower case, in any order, separated by blanks or commas, as desired. Single quotes are not necessary, e.g., esx is a legitimate input line.

The data points should be of the form (independent variable, dependent variable). Both the independent and dependent variables must contain decimal points and must be separated by a comma, e.g., (123.,456.789). If no data points are missing, it is not necessary to list each independent variable; instead, a zero or any other number can be substituted (0.,456.789).

Table 1 lists an example of an input file where no data points are missing; in particular, this is the file used to generate Figure 1. The first line lists the options. For this case, we want the program to echo the input and smooth both the data and the errors. Lines 2 through 30 list the 29 sets of data points in proper format. It is not necessary to count the data points; the program automatically counts them and stops




Figure 1. Data Before and After Using the FIT Program

reading data when it reaches end-of-file.

Table 2 gives another example. In this instance, some of the data are missing. Line one of the file asks for the missing points to be filled in as well as for the input to be echoed, for the data to be smoothed, and for the errors not to be smoothed. The second line, one number which must contain a decimal point, specifies the maximum number of data points to be filled in between raw data values. (Please note, this number is not the total number of missing points.) This line is used only when the "f" option is chosen -- don't forget it. Lines 3 through 27 list the sets of data points.

Table 1. Sample Data File I (No Missing Values)

Line Number	Data in File	Explanation
01	es	Options
02	1.,138.,	Data Points
03	2.,62.,	"
04	3.,138.,	"
05	4.,63.,	"
06	5.,20.,	"
07	6.,4.,	"
08	7.,29.,	"
09	8.,130.,	"
10	9.,304.,	"
11	10.,223.,	"
12	11.,876.,	"
13	12.,563.,	"
14	13.,696.,	"
15	14.,508.,	"
16	15.,384.,	"
17	16.,255.,	"
18	17.,439.,	"
19	18.,529.,	"
20	19.,336.,	"
21	20.,492.,	"
22	21.,530.,	"
23	22.,498.,	"
24	23.,403.,	"
25	24.,550.,	"
26	25.,434.,	"
27	26.,747.,	"
28	27.,721.,	"
29	28.,747.,	"
30	29.,1122.,	"

Table 2. Sample Data File II (Missing Values)

Line Number	Data in File	Explanation
01	f e s n	Options
02	5.	Between raw, max # filled-in
03	1.,138.,	Data Points
04	2.,62.,	"
05	3.,138.,	"
06	5.,20.,	"
07	6.,4.,	"
08	7.,29.,	"
09	8.,130.,	"
10	9.,304.,	"
11	10.,223.,	"
12	11.,876.,	"
13	12.,563.,	"
14	13.,696.,	"
15	16.,255.,	"
16	17.,439.,	"
17	18.,529.,	"
18	19.,336.,	"
19	20.,492.,	"
20	22.,498.,	"
21	23.,403.,	"
22	24.,550.,	"
23	25.,434.,	"
24	26.,747.,	"
25	27.,721.,	"
26	28.,747.,	"
27	29.,1122.,	"

## OUTPUT

The output files vary depending on the options chosen as well as on the data. In general, the first few lines describe the options; while, ensuing lines list the subroutines as entered, an explanation of the procedure, and the data at various stages. Table 3 gives the output for Sample Data File I from Table 1. The smoothed data you would use for further study is listed under the column "new x(i)" near the end of the listing. The column labeled "orig x(i)" list the original input data and "err (i)" represents the errors between the original and the new data. The "Sigma of err(i)" is the standard deviation of the errors.

Table 4 gives the output for Sample Data File II. Now, when the program enters the input subroutine, it first reads a value, "m0," which represents the maximum number of filled-in points between real data points, before it reads the data points.

Table 3. Output File for Sample Data File I

Echoing input  
Smoothing data  
In input subroutine

i	t(i)	x(i)
0	1.0000e+00	1.3800e+02
1	2.0000e+00	6.2000e+01
2	3.0000e+00	1.3800e+02
3	4.0000e+00	6.3000e+01
4	5.0000e+00	2.0000e+01
5	6.0000e+00	4.0000e+00
6	7.0000e+00	2.9000e+01
7	8.0000e+00	1.3000e+02
8	9.0000e+00	3.0400e+02
9	1.0000e+01	2.2300e+02
10	1.1000e+01	8.7600e+02
11	1.2000e+01	5.6300e+02
12	1.3000e+01	6.9600e+02
13	1.4000e+01	5.0800e+02
14	1.5000e+01	3.8400e+02
15	1.6000e+01	2.5500e+02
16	1.7000e+01	4.3900e+02
17	1.8000e+01	5.2900e+02
18	1.9000e+01	3.3600e+02
19	2.0000e+01	4.9200e+02
20	2.1000e+01	5.3000e+02
21	2.2000e+01	4.9800e+02
22	2.3000e+01	4.0300e+02
23	2.4000e+01	5.5000e+02
24	2.5000e+01	4.3400e+02
25	2.6000e+01	7.4700e+02
26	2.7000e+01	7.2100e+02
27	2.8000e+01	7.4700e+02
28	2.9000e+01	1.1220e+03

In smoothing routine

Perform 3R<sup>SH</sup> smoothing on the x(i) values,  
i.e., smooth by repeated medians of 3 (3R)  
up to 3 times, split two-point peaks and valleys  
twice (doing 3R after each split), then hann.

Subtracting the smoothed data from the original data  
yields some errors -- called the rough

- In median routine
- In median routine
- In median routine
- In splitting routine
- In median routine
- In median routine

Table 3. Output File for Sample Data File I (cont'd)

- In splitting routine
- In median routine
- In median routine
- In hanning routine

i	original	smooth	rough
0	1.3800e+02	6.3000e+01	7.5000e+01
1	6.2000e+01	6.3000e+01	-1.0000e+00
2	1.3800e+02	6.3000e+01	7.5000e+01
3	6.3000e+01	6.3000e+01	0. e+00
4	2.0000e+01	6.3000e+01	-4.3000e+01
5	4.0000e+00	6.3000e+01	-5.9000e+01
6	2.9000e+01	7.9750e+01	-5.0750e+01
7	1.3000e+02	1.3650e+02	-6.5000e+00
8	3.0400e+02	2.2000e+02	8.4000e+01
9	2.2300e+02	3.4850e+02	-1.2550e+02
10	8.7600e+02	4.9825e+02	3.7775e+02
11	5.6300e+02	5.6300e+02	0. e+00
12	6.9600e+02	5.4925e+02	1.4675e+02
13	5.0800e+02	5.0450e+02	3.5000e+00
14	3.8400e+02	4.5625e+02	-7.2250e+01
15	2.5500e+02	4.3900e+02	-1.8400e+02
16	4.3900e+02	4.3900e+02	0. e+00
17	5.2900e+02	4.5225e+02	7.6750e+01
18	3.3600e+02	4.7875e+02	-1.4275e+02
19	4.9200e+02	4.9350e+02	-1.5000e+00
20	5.3000e+02	4.9650e+02	3.3500e+01
21	4.9800e+02	4.9800e+02	0. e+00
22	4.0300e+02	4.9800e+02	-9.5000e+01
23	5.5000e+02	5.1100e+02	3.9000e+01
24	4.3400e+02	5.7975e+02	-1.4575e+02
25	7.4700e+02	6.8475e+02	6.2250e+01
26	7.2100e+02	7.4050e+02	-1.9500e+01
27	7.4700e+02	7.6000e+02	-1.3000e+01
28	1.1220e+03	7.9900e+02	3.2300e+02

Now, smooth the rough with 3RSSH

- In median routine
- In median routine
- In median routine
- In splitting routine
- In median routine
- In median routine
- In splitting routine
- In median routine
- In median routine
- In hanning routine

Table 3. Output File for Sample Data File I (cont'd)

Re-rough the initial smooth by adding the smooth of rough  
 i.e., new x(i) = smooth of smooth + smooth of rough

i	orig x(i)	new x(i)	err(i)
0	1.3800e+02	6.3000e+01	7.5000e+01
1	6.2000e+01	6.3000e+01	-1.0000e+00
2	1.3800e+02	6.3000e+01	7.5000e+01
3	6.3000e+01	6.3000e+01	0. e+00
4	2.0000e+01	6.1375e+01	-4.1375e+01
5	4.0000e+00	5.8125e+01	-5.4125e+01
6	2.9000e+01	7.3250e+01	-4.4250e+01
7	1.3000e+02	1.3000e+02	0. e+00
8	3.0400e+02	2.1513e+02	8.8875e+01
9	2.2300e+02	3.4775e+02	-1.2475e+02
10	8.7600e+02	5.0088e+02	3.7513e+02
11	5.6300e+02	5.6650e+02	-3.5000e+00
12	6.9600e+02	5.5275e+02	1.4325e+02
13	5.0800e+02	5.0800e+02	0. e+00
14	3.8400e+02	4.5888e+02	-7.4875e+01
15	2.5500e+02	4.3988e+02	-1.8488e+02
16	4.3900e+02	4.3900e+02	0. e+00
17	5.2900e+02	4.5225e+02	7.6750e+01
18	3.3600e+02	4.7875e+02	-1.4275e+02
19	4.9200e+02	4.9350e+02	-1.5000e+00
20	5.3000e+02	4.9650e+02	3.3500e+01
21	4.9800e+02	4.9800e+02	0. e+00
22	4.0300e+02	4.9800e+02	-9.5000e+01
23	5.5000e+02	5.0775e+02	4.2250e+01
24	4.3400e+02	5.7000e+02	-1.3600e+02
25	7.4700e+02	6.7175e+02	7.5250e+01
26	7.2100e+02	7.2750e+02	-6.5000e+00
27	7.4700e+02	7.4700e+02	0. e+00
28	1.1220e+03	7.8600e+02	3.3600e+02

Sigma of err(i) = 122.131

Table 4. Output File for Sample Data File II

Echoing input  
 Equalizing data by filling in  
 Smoothing data  
 Not re-roughing the initial smoothed data  
 In input subroutine  
 max number of interpolated points between real data points, m0 = 5.00000  

i	t(i)	x(i)
0	1.0000e+00	1.3800e+02
1	2.0000e+00	6.2000e+01
2	3.0000e+00	1.3800e+02
3	5.0000e+00	2.0000e+01
4	6.0000e+00	4.0000e+00
5	7.0000e+00	2.9000e+01
6	8.0000e+00	1.3000e+02
7	9.0000e+00	3.0400e+02
8	1.0000e+01	2.2300e+02
9	1.1000e+01	8.7600e+02
10	1.2000e+01	5.6300e+02
11	1.3000e+01	6.9600e+02
12	1.6000e+01	2.5500e+02
13	1.7000e+01	4.3900e+02
14	1.8000e+01	5.2900e+02
15	1.9000e+01	3.3600e+02
16	2.0000e+01	4.9200e+02
17	2.2000e+01	4.9800e+02
18	2.3000e+01	4.0300e+02
19	2.4000e+01	5.5000e+02
20	2.5000e+01	4.3400e+02
21	2.6000e+01	7.4700e+02
22	2.7000e+01	7.2100e+02
23	2.8000e+01	7.4700e+02
24	2.9000e+01	1.1220e+03

 In fill subroutine  

i	filled t(i)	filled x(i)
0	1.0000e+00	1.3800e+02
1	2.0000e+00	6.2000e+01
2	3.0000e+00	1.3800e+02
3	4.0000e+00	7.9000e+01
4	5.0000e+00	2.0000e+01
5	6.0000e+00	4.0000e+00
6	7.0000e+00	2.9000e+01
7	8.0000e+00	1.3000e+02
8	9.0000e+00	3.0400e+02
9	1.0000e+01	2.2300e+02
10	1.1000e+01	8.7600e+02
11	1.2000e+01	5.6300e+02

Table 4. Output File for Sample Data File II (cont'd)

12	1.3000e+01	6.9600e+02
13	1.4000e+01	5.4900e+02
14	1.5000e+01	4.0200e+02
15	1.6000e+01	2.5500e+02
16	1.7000e+01	4.3900e+02
17	1.8000e+01	5.2900e+02
18	1.9000e+01	3.3600e+02
19	2.0000e+01	4.9200e+02
20	2.1000e+01	4.9500e+02
21	2.2000e+01	4.9800e+02
22	2.3000e+01	4.0300e+02
23	2.4000e+01	5.5000e+02
24	2.5000e+01	4.3400e+02
25	2.6000e+01	7.4700e+02
26	2.7000e+01	7.2100e+02
27	2.8000e+01	7.4700e+02
28	2.9000e+01	1.1220e+03

In smoothing routine

Perform 3RSSH smoothing on the x(i) values,  
 i.e., smooth by repeated medians of 3 (3R)  
 up to 3 times, split two-point peaks and valleys  
 twice (doing 3R after each split), then hann.  
 Subtracting the smoothed data from the original data  
 yields some errors -- called the rough

- In median routine
- In median routine
- In median routine
- In splitting routine
- In median routine
- In median routine
- In splitting routine
- In median routine
- In median routine
- In hanning routine

i	original	smooth	rough
0	1.3800e+02	7.9000e+01	5.9000e+01
1	6.2000e+01	7.9000e+01	-1.7000e+01
2	1.3800e+02	7.9000e+01	5.9000e+01
3	7.9000e+01	7.9000e+01	0. e+00
4	2.0000e+01	7.9000e+01	-5.9000e+01
5	4.0000e+00	7.9000e+01	-7.5000e+01
6	2.9000e+01	9.1750e+01	-6.2750e+01
7	1.3000e+02	1.4050e+02	-1.0500e+01
8	3.0400e+02	2.2000e+02	8.4000e+01
9	2.2300e+02	3.4850e+02	-1.2550e+02

Table 4. Output File for Sample Data File II (cont'd)

10	8.7600e+02	4.9825e+02	3.7775e+02
11	5.6300e+02	5.6300e+02	0. e+00
12	6.9600e+02	5.5950e+02	1.3650e+02
13	5.4900e+02	5.4550e+02	3.5000e+00
14	4.0200e+02	5.0750e+02	-1.0550e+02
15	2.5500e+02	4.5950e+02	-2.0450e+02
16	4.3900e+02	4.3900e+02	0. e+00
17	5.2900e+02	4.5225e+02	7.6750e+01
18	3.3600e+02	4.7875e+02	-1.4275e+02
19	4.9200e+02	4.9275e+02	-7.5000e-01
20	4.9500e+02	4.9425e+02	7.5000e-01
21	4.9800e+02	4.9500e+02	3.0000e+00
22	4.0300e+02	4.9575e+02	-9.2750e+01
23	5.5000e+02	5.1025e+02	3.9750e+01
24	4.3400e+02	5.7975e+02	-1.4575e+02
25	7.4700e+02	6.8475e+02	6.2250e+01
26	7.2100e+02	7.4050e+02	-1.9500e+01
27	7.4700e+02	7.6000e+02	-1.3000e+01
28	1.1220e+03	7.9900e+02	3.2300e+02

Sigma of err(i) = 123.050

Then, the program continues into the fill subroutine where "m0" is tested. If this value had been too small, the program would have printed an error message and stopped (See Table 5). Given that this has not happened, a new set of data points are printed. The original data have not been altered; just additional points have been added. The program continues through the rest of the subroutines as before, but, since we asked for no smoothing of the errors, it stops earlier. Now, the smoothed data to be used for further study is listed under the column "smooth" near the end of the listing; whereas, the column "rough" represents the errors between the smooth and the original data. The standard deviation of the rough is given by "Sigma of err(i)."

Table 5. Sample Output File When Inadequate Fill-In Parameter Given

Echoing input  
 Equalizing data by filling in  
 Smoothing data  
 Not re-roughing the initial smoothed data  
 In input subroutine  
 max number of interpolated points between real data points, m0 = 1.00000  

i	t(i)	x(i)
0	1.0000e+00	1.3800e+02
1	2.0000e+00	6.2000e+01
2	3.0000e+00	1.3800e+02
3	5.0000e+00	2.0000e+01
4	6.0000e+00	4.0000e+00
5	7.0000e+00	2.9000e+01
6	8.0000e+00	1.3000e+02
7	9.0000e+00	3.0400e+02
8	1.0000e+01	2.2300e+02
9	1.1000e+01	8.7600e+02
10	1.2000e+01	5.6300e+02
11	1.3000e+01	6.9600e+02
12	1.6000e+01	2.5500e+02
13	1.7000e+01	4.3900e+02
14	1.8000e+01	5.2900e+02
15	1.9000e+01	3.3600e+02
16	2.0000e+01	4.9200e+02
17	2.2000e+01	4.9800e+02
18	2.3000e+01	4.0300e+02
19	2.4000e+01	5.5000e+02
20	2.5000e+01	4.3400e+02
21	2.6000e+01	7.4700e+02
22	2.7000e+01	7.2100e+02
23	2.8000e+01	7.4700e+02
24	2.9000e+01	1.1220e+03

 In fill subroutine  
 Equalizing step size is impossible;  
 3.00000 is greater than m0 = 1.00000

## METHODOLOGY

The program described above uses the 3RSSH method of Tukey for smoothing the data.<sup>1</sup> First, we will decipher the acronym and, then, describe the techniques. 3R stands for Repeated medians of 3. SS is Splitting of two-point peaks and valleys -- done twice; while H is Hanning.

With 3R, the program takes the first three dependent values (0, 1, and 2), finds the median, and stores that in a new array as point 1. Next, it takes points 1 through 3, finds the median, and stores that as new point 2. This process continues until it takes points N-2, N-1, and N and stores their median in point N-1. To complete the new array, the program just copies points 0 and N onto it. If this new array is equal to the original array, 3R is stopped; otherwise, this process continues until no changes take place or a total of three times, whichever comes first. However, the second iteration starts with point 1 and continues through N-1 (copying on points 0, 1, N-1, and N); while the third iteration starts at point 2 and goes to N-2 (copying points 0, 1, 2, N-2, N-1, and N). Whenever 3R is completed, these copied-on, end values need smoothing which is done by finding the median of the end value, the last smoothed value, and the difference between thrice the last smoothed value and twice the next-to-last smoothed value. For example, if 3R has been performed three times, the points 0, 1, 2, N-2, N-1, and N all need smoothed. For point 0, the formula would be:

$$\text{new point 0} = \text{median}(\text{point 0}, \text{point 3}, 3*(\text{point 3}) - 2*(\text{point 4})).$$

For points 1 and 2, the same formula applies with just the substitution of these points for point 0. To find points N-2, N-1 and N, just substitute each of these, in turn, for point 0 and change point 3 to point N-3 and point 4 to point N-4.

To perform the splitting portion of 3RSSH, the program examines the 3R data to see if there are any peaks or valleys consisting of just two, equal data points. If so, they are split apart and end-point smoothing (the same formula as previous paragraph) is performed on each point as if it were the last. In this case, however, the last and next-to-last smoothed data points are now adjacent to the end points, i. e., if the peak values are  $i$  and  $i+1$ , then we would use points  $i$ ,  $i-1$ , and  $i-2$  to determine the new point  $i$ , and  $i+1$ ,  $i+2$ ,  $i+3$  to determine the new point  $i+1$ . When all such pairs have been examined, another 3R is done on the data. This entire process is repeated with another split and 3R. However, if there were no splits, the program immediately goes to the hanning subroutine, since no changes have occurred in the data.

In the hanning technique, the program, first, runs through the data set and finds the mid-range between every other data point, which becomes a tentative new value for the intermediate data point. Then, it finds the mean of the original, intermediate value and the tentative value. This mean becomes the newest value for each data point in the set. For example, let the original data set be the values 4, 5, 6, 8, 11. The mid-ranges would be  $(4+6)/2$ ,  $(5+8)/2$ ,  $(6+11)/2$ . The means, the averages of the mid-range and

---

<sup>1</sup> John W. Tukey, Exploratory Data Analysis, Reading, Massachusetts, Addison-Wesley Publishing Company, Inc., 1977, pp 204-236 and 523-542.

the original number, would be  $(5+5)/2$ ,  $(6.5+6)/2$ ,  $(8.5+8)/2$ . Therefore, the final set of values would be 4, 5, 6.25, 8.25, 11.

Hanning finishes the 3RSSH process and its resultant data set is called the smooth. This smooth is then subtracted from the original data to obtain the errors, also known as the rough. To obtain a better smooth, it is a good idea to perform 3RSSH on this rough. The smooth we obtain from the rough is then added to the first smooth yielding a final smooth and a final rough.

## SUMMARY

The FIT program enables you to smooth sequential data to observe the inherent trends. It is easily used without much knowledge of the underlying techniques and can be employed repeatedly to the subsequent smoothed data sets to achieve whatever smoothness is desired.

## REFERENCES

1. John W. Tukey, Exploratory Data Analysis, Reading, Massachusetts, Addison-Wesley Publishing Company, Inc., 1977, pp 204-236 and 523-542.

## Appendix: Program Listing

```
c Purpose: Fit data
logical ECHO, FILLIN, SMOOTH, XTRA, NRERUF
logical isarg
character*1 arg
dimension arg(40)
common /misc/ ECHO, FILLIN, XTRA, NRERUF
format(40a1)

1 c
read(5,1) arg
ECHO  = isarg('e',arg)
FILLIN = isarg('f',arg)
SMOOTH = isarg('s',arg)
XTRA  = isarg('x',arg)
NRERUF = isarg('n',arg)
if (ECHO ) print *, ' Echoing input'
if (FILLIN) print *, ' Equalizing data by filling in'
if (SMOOTH) print *, ' Smoothing data'
if (XTRA ) print *, ' Extra printing of intermediate results'
if (NRERUF) print *, ' Not re-roughing the initial smoothed data'
call input(em0)
c call equalizing routine to fill in missing data
     if (FILLIN) call fill(em0)
     if (SMOOTH) call smoth
END

c
c LOGICAL FUNCTION IS ARG ( ACHAR, ARG)
c -----
c Return true iff achar is in arg
character*1 achar
character*1 arg
dimension arg(40)

c
is arg = .FALSE.
c Loop through each element of arg until ACHAR is found.
    DO 30 narg = 1,40
        IF ( ACHAR .eq. arg(narg)) THEN
            is arg = .TRUE.
                                            GOTO 99
30     ENDIF
        CONTINUE
99     CONTINUE
END

c
c SUBROUTINE INPUT ( em0 )
c -----
logical sorted, ECHO, FILLIN, XTRA, NRERUF
common/data/tt(0:749),x(0:749),n
common /misc/ ECHO, FILLIN, XTRA, NRERUF
1 format (i8,2(1pe12.4))
2 print *, 'In input subroutine'
2 format(2f12.4)
```

```

c      if FILLIN is true (FILL is used), then
c      read em0, where em0 is the maximum number off interpolated
c      points between real data points
c      IF (FILLIN) THEN
c          read 2, em0
c          if (ECHO) print *, ' max number of interpolated points'
1      , 'between real data points, m0 =', em0
c      .ENDIF
c      if (ECHO) print *, '      i      t(i)      x(i)'
c      DO 10 i = 0,749
c          read(5,2,END=500) tt(i), x(i)
c          if (ECHO) print 1, i,tt(i),x(i)
10    CONTINUE
500   n = i - 1
c      DO 20 i = 1,n-1
c          sorted = .true.
c          DO 30 nn = 0,n-1
c              if (tt(nn) .le. tt(nn+1)) go to 30
c              temp = tt(nn)
c              tt(nn) = tt(nn+1)
c              tt(nn+1) = temp
c              temp = x(nn)
c              x(nn) = x(nn+1)
c              x(nn+1) = temp
c              sorted = .false.
30    CONTINUE
c          if (sorted) go to 40
20    CONTINUE
40    CONTINUE
c      delta = (tt(n) - tt(0)) / n
c      END
c
c      SUBROUTINE FILL ( em0 )
c -----
logical sorted, ECHO, FILLIN, XTRA, NRERUF
integer p
dimension deltan(750),z(0:749),t(0:750),tp(0:749)
common/data/tt(0:749),x(0:749),n
common /misc/ ECHO, FILLIN, XTRA, NRERUF
print *, 'In fill subroutine'
c ***** store independent variable tt into t since t needs to be
c ***** one longer
c      DO 5 nn = 0,n
c          t(nn) = tt(nn)
5     CONTINUE
c ***** find the differences between each indep. variable
c      DO 10 nn = 1,n
c          deltan(nn) = t(nn) - t(nn-1)
10    CONTINUE
c ***** now sort these differences
c      DO 20 i = 1,nn-1
c          sorted = .true.
c          DO 30 nn = 1,n-1
c              if (deltan(nn) .le. deltan(nn+1)) go to 30

```

```

temp = deltan(nn)
deltan(nn) = deltan(nn+1)
deltan(nn+1) = temp
sorted = .false.

30      CONTINUE
        if (sorted) go to 40
20      CONTINUE
c ***** now find median and maximum of these "delta's"
40      IF (mod(n,2) .ne. 0) THEN
        delmed = deltan(n/2 + 1)
        ELSE
        delmed = (deltan(n/2) + deltan(n/2 + 1)) / 2.
        ENDIF
        delmax = deltan(n)
        ncap1 = (t(n) - t(0))/delmed
        if (ncap1 .ne. (t(n) - t(0))/delmed) ncap1 = ncap1 + 1
        delta = (t(n) - t(0)) / ncap1
        t(n+1) = 1.e20
        if (delmax/delta .gt. em0) go to 100
c ***** equalize step size and fill in data
        DO 50 p = 0, ncap1
            tp(p) = t(0) + p*delta
            DO 60 nn = 0,n
                if((t(nn) .le. tp(p)) .and. (tp(p) .lt. t(nn+1))) go to 70
60      CONTINUE
70      z(p) = ((tp(p) -t(nn))*x(nn+1) + (t(nn+1) -tp(p))*x(nn)) /
                (t(nn+1) -t(nn))
1      50 CONTINUE
        n = ncap1
        print *, '      i filled t(i) filled x(i)'
        DO 80 nn = 0,n
            x(nn) = z(nn)
            print 1, nn,tp(nn),x(nn)
80      CONTINUE
        RETURN
100     dlmd1 = delmax/delta
        print *, ' Equalizing step size is impossible; '
        print *, dlmd1,
1      ' is greater than m0 =',em0
        STOP
1      format(i8,2(1pe12.4))
        END
c
c      SUBROUTINE SMOOTH
-----
logical done, ECHO, FILLIN, XTRA, NRERUF
dimension y(0:749), xhat(0:749), err(0:749), z(0:749)
common/data/tt(0:749),x(0:749),n
common /misc/ ECHO, FILLIN, XTRA, NRERUF
1      format (i8,3(1pe12.4))
c
c      print *, 'In smoothing routine'
c      print *, ' Perform 3RSSH smoothing on the x(i) values, '
c      print *, ' i.e., smooth by repeated medians of 3 (3R)'


```

```

print *, ' up to 3 times, split two-point peaks and valleys'
print *, ' twice (doing 3R after each split), then hann.'
print *, ' Subtracting the smoothed data from the original data'
print *, ' yields some errors -- called the rough'
c   Store a copy of x into y
call copy(n,x,y)
c   Smooth by medians 3 times or until no more changes (3R)
done = .false.
DO 10 i = 1,3
    IF (done) GOTO 15
    call median(n,y,done,i)
10  CONTINUE
15  CONTINUE
c   Split twice or until no more splits (SS)
done = .false.
DO 20 nsplit = 1,2
    call split(done,n,y)
    IF (XTRA) THEN
        print *, '      i  new value'
        DO 22 ijk=0,n
            print 1, ijk, y(ijk)
22  CONTINUE
    ENDIF
    IF (done) GOTO 25
c   If there's no splits then exit loop
c   Otherwise 3R the new split values
    DO 23 i=1,3
        IF (done) GOTO 24
        call median(n,y,done,i)
23  CONTINUE
24  CONTINUE
done = .false.
20  CONTINUE
25  CONTINUE
    IF (XTRA) THEN
        print *, '      i  new value'
        DO 27 ijk=0,n
            print 1, ijk, y(ijk)
27  CONTINUE
    ENDIF
c   Hann the 3RSS data (H)
    call haning(n,y,z)
c   Store this 3RSSH smoothed data into xhat
    call copy(n,z,xhat)
c   Find the rough of the smoothed data
c   And, print the original and 3RSSH smooth & rough
    print *, '      i  original  smooth  rough'
    sum sq = 0.
    DO 30 i=0,n
        y(i) = x(i)-xhat(i)
        if (NRERUF) sum sq = sum sq + y(i)**2
        print 1, i, x(i), xhat(i), y(i)
30  CONTINUE
    IF ( .not. NRERUF) THEN

```

```

c      3RSS and Hann the rough of initial 3RSSH
c      Smooth by medians 3 times or until no more changes
      print *, ' Now, smooth the rough with 3RSSH'
      done = .false.
      DO 32 i = 1,3
          IF (done)      GOTO 34
          call median(n,y,done,i)
32    CONTINUE
34    CONTINUE
c      Split twice or until no more splits
      done = .false.
      DO 35 nsplit = 1,2
          call split(done,n,y)
      IF (XTRA) THEN
          print *, '      i  new value'
          DO 36 ijk=0,n
              print 1, ijk, y(ijk)
36    CONTINUE
      ENDIF
          IF (done)      GOTO 39
c      If there's no splits then exit loop
c      Otherwise 3R the new split values
          DO 37 i=1,3
              IF (done) GOTO 38
              call median(n,y,done,i)
37    CONTINUE
38    CONTINUE
          done = .false.
35    CONTINUE
39    CONTINUE
      IF (XTRA) THEN
          print *, '      i  new value'
          DO 41 ijk=0,n
              print 1, ijk, y(ijk)
41    CONTINUE
      ENDIF
c      Hann the 3RSS of the rough
      call haning(n,y,z)
      IF (XTRA) THEN
          print *, '      i smooth of rough'
          DO 43 ijk=0,n
              print 1, ijk, z(ijk)
43    CONTINUE
      ENDIF
          sum sq = 0.
c      Re-rough by adding the smooth of the rough to the initial smooth
c      to find the final smooth
c      and find the error between orig. data and final smooth
          print *, ' Re-rough the initial smooth by adding the smooth of rough'
          print *, ' i.e., new x(i) = smooth of smooth + smooth of rough'
          print *, '      i  orig x(i)  new x(i)  err(i)'
          DO 40 i=0,n
              xhat(i) = xhat(i) + z(i)
              err(i) = x(i) - xhat(i)

```

```

        sum sq = sum sq+err(i)**2
        print 1, i, x(i), xhat(i), err(i)
        x(i) = xhat(i)
40    CONTINUE
        ENDIF
        sigma s = sqrt(sum sq/n)
        print *, 'Sigma of err(i) = ', sigma s
    END
c
c      SUBROUTINE MEDIAN(n,y,done,k)
c
c      Smooth by taking medians of 3
c      real medin
c      logical done,mdone,ECHO,FILLIN,XTRA,NRERUF
c      common /misc/ ECHO, FILLIN, XTRA, NRERUF
c      dimension y(0:749),z(0:749)
1      format (i8,2(1pe12.4))
c
c      print *, '- In median routine'
c      mdone = .true.
c      Copy on the end input values
        DO 5 i = 0,k-1
            z(i) = y(i)
5    CONTINUE
        DO 10 i = n-k+1,n
            z(i) = y(i)
10   CONTINUE
c      Start the median-taking at the k-th element
        DO 20 i=k,n-k
            z(i) = medin(y(i-1),y(i),y(i+1))
            if( z(i) .ne. y(i) ) mdone = .false.
20   CONTINUE
c      Smooth end input values when medians of 3 are finished
c      either when no more changes have taken place or when
c      k reaches 3
        IF (. (mdone) .or. (k .eq. 3) ) THEN
            DO 32 i = 0,k-1
                z(i) = medin(3*z(k)-2*z(k+1),y(i),z(k))
32   CONTINUE
            DO 37 i = n-k+1,n
                z(i) = medin(z(n-k),y(i),3*z(n-k)-2*z(n-k-1))
37   CONTINUE
        ENDIF
        if (XTRA) print *, '      i    old value    new value'
        DO 40 i=0,n
            if (XTRA) print 1, i, y(i), z(i)
            y(i) = z(i)
40   CONTINUE
        done = mdone
    END
c
c      SUBROUTINE SPLIT(done,n,y)
c
c      perform splitting of data at plateaus

```

```

logical done,nsplit
real medin
dimension y(0:749),z(0:749)

c
print *,'- In splitting routine'
nsplit = .true.

c ** change from do-loop because incrementing of loop index
c ** while in the loop is not allowed by all compilers
c      DO 10 i=2,n-3
c      i = 2
c      if data not equal leave alone
7       if(y(i) .eq. y(i+1)) GO TO 5
2       z(i) = y(i)
       GO TO 10
c      if two adjacent data points equal and slope continuing in
c      same direction; leave alone
5       if ( (y(i) .eq. y(i+2)) .or. (y(i) .eq. y(i-1)) ) GOTO 2
c       if(sign(1.,y(i)-y(i-1)).ne.sign(1.,y(i+1)-y(i+2))) GO TO 2
c      else
c      smooth out plateau by giving these two points new values
c      also change nsplit to indicate a splitting
c      nsplit = .false.
c      z(i) = medin(3*y(i-1)-2*y(i-2),y(i-1),y(i))
c      z(i+1) = medin(3*y(i+2)-2*y(i+3),y(i+2),y(i+1))
c      i = i+1
10      CONTINUE
c      ** next two lines replace do-loop increment and test
c      i = i + 1
c      if (i .le. n-3) goto 7
c      DO 20 i=2,n-3
c      y(i) = z(i)
20      CONTINUE
c      if(nsplit) done = .true.
c      END

c
SUBROUTINE HANING (n,y,z)
-----
c
Perform hanning's smoothing method
dimension y(0:749), z(0:749)

c
print *,'- In hanning routine'
DO 20 i=1,n-1
      z(i) = 0.25*(y(i-1)+2*y(i)+y(i+1))
20      CONTINUE
      z(0) = y(0)
      z(n) = y(n)
c      END

c
SUBROUTINE COPY (n, x, y)
-----
c
Copy vector of length n from x to y
dimension x(0:749), y(0:749)
DO 20 i=0,n
      y(i) = x(i)

```

```
20      CONTINUE
      END
c      REAL FUNCTION MEDIN (a, b, c)
c      -----
c      Find the median of a, b, c
      IF (sign(1.,a-b) .eq. sign(1.,b-c)) THEN
          medin = b
      ELSE IF (abs(a-b) .gt. abs(b-c)) THEN
          medin = c
      ELSE
          medin = a
      ENDIF
      END
```

DISTRIBUTION LIST

No. of Copies	<u>Organization</u>	No. of Copies	<u>Organization</u>
12	Administrator Defense Technical Info Center ATTN: DTIC-DDA Cameron Station Alexandria, VA 22314	1	Director US Army Air Mobility Research and Development Laboratory Ames Research Center Moffett Field, CA 94035
1	HQDA DAMA-ART-M Washington, DC 20310	1	Commander US Army Communications- Electronics Command ATTN: AMSEL-ED Fort Monmouth, NJ 07703
1	Commander US Army Materiel Command ATTN: AMCDRA-ST 5001 Eisenhower Avenue Alexandria, VA 22333-0001	1	Commander ERADCOM Technical Library ATTN: DELSD-L (Reports Section) Fort Monmouth, NJ 07703-5301
1	Commander Armament R&D Center US Army AMCCOM ATTN: SMCAR-TDC Dover, NJ 07801-5001	1	Commander US Army Tank Automotive Command ATTN: AMSTA-TSL Warren, MI 48090
1	Commander Armament R&D Center US Army AMCCOM ATTN: SMCAR-TSS Dover, NJ 07801-5001	1	Commander US Army Missile Command Research, Development and Engineering Center ATTN: AMSMI-RD Redstone Arsenal, AL 35898
1	Commander US Army Armament, Munitions & Chemical Command ATTN: SMCAR-ESP-L Rock Island, IL 61299-6000	1	Commander US Army Missile and Space Intelligence Center ATTN: AIAMS-YDL Redstone Arsenal, AL 35898-5500
1	Director Benet Weapons Laboratory Armament R&D Center US Army AMCCOM ATTN: SMCAR-LCB-TL Watervliet, NY 12189	1	Director US Army TRADOC Systems Analysis Activity ATTN: ATAA-SL White Sands Missile Range, NM 88002
1	Commander US Army Aviation Research and Development Command ATTN: AMSAV-E 4300 Goodfellow Boulevard St. Louis, MO 63120	1	Air Force Armament Laboratory ATTN: AFATL/DLODL Eglin AFB, FL 32542-5000
		1	Commandant US Army Infantry School ATTN: ATSH-CD-CSO-OR Fort Benning, GA 31905

DISTRIBUTION LIST

No. of  
Copies      Organization

1 Commander  
US Army Development & Employment  
Agency  
ATTN: MODE-TED-SAB  
Fort Lewis, WA 98433

1 AFWL/SUL  
Kirtland AFB, NM 87117

Aberdeen Proving Ground

Dir, USAMSA  
ATTN: AMXSY-D  
AMXSY-MP, Mr. H. Cohen

Cdr, USATECOM  
ATTN: AMSTE-TO-F

Cdr, CRDC, AMCCOM  
ATTN: SMCCR-RSP-A  
SMCCR-MU  
SMCCR-SPS-IL

## USER EVALUATION SHEET/CHANGE OF ADDRESS

This Laboratory undertakes a continuing effort to improve the quality of the reports it publishes. Your comments/answers to the items/questions below will aid us in our efforts.

1. BRL Report Number \_\_\_\_\_ Date of Report \_\_\_\_\_

2. Date Report Received \_\_\_\_\_

3. Does this report satisfy a need? (Comment on purpose, related project, or other area of interest for which the report will be used.)  
\_\_\_\_\_  
\_\_\_\_\_

4. How specifically, is the report being used? (Information source, design data, procedure, source of ideas, etc.)  
\_\_\_\_\_  
\_\_\_\_\_

5. Has the information in this report led to any quantitative savings as far as man-hours or dollars saved, operating costs avoided or efficiencies achieved, etc? If so, please elaborate.  
\_\_\_\_\_  
\_\_\_\_\_

6. General Comments. What do you think should be changed to improve future reports? (Indicate changes to organization, technical content, format, etc.)  
\_\_\_\_\_  
\_\_\_\_\_

CURRENT ADDRESS Name \_\_\_\_\_

Organization \_\_\_\_\_

Address \_\_\_\_\_

City, State, Zip \_\_\_\_\_

7. If indicating a Change of Address or Address Correction, please provide the New or Correct Address in Block 6 above and the Old or Incorrect address below.

OLD ADDRESS Name \_\_\_\_\_

Organization \_\_\_\_\_

Address \_\_\_\_\_

City, State, Zip \_\_\_\_\_

(Remove this sheet along the perforation, fold as indicated, staple or tape closed, and mail.)

— — — — — FOLD HERE — — — — —

Director  
U.S. Army Ballistic Research Laboratory  
ATTN: SLCBR-DD-T  
Aberdeen Proving Ground, MD 21005-5066




NO POSTAGE  
NECESSARY  
IF MAILED  
IN THE  
UNITED STATES

OFFICIAL BUSINESS  
PENALTY FOR PRIVATE USE. \$300

**BUSINESS REPLY MAIL**  
FIRST CLASS PERMIT NO 12062 WASHINGTON, DC  
POSTAGE WILL BE PAID BY DEPARTMENT OF THE ARMY

Director  
U.S. Army Ballistic Research Laboratory  
ATTN: SLCBR-DD-T  
Aberdeen Proving Ground, MD 21005-9989



— — — — — FOLD HERE — — — — —

**END**

**FILMED**

**12-85**

**DTIC**